

15 MAR 1944

"HABANA"Rpt. Bbo. No. 9584.

In view of the Bilbao Surveyors' letter of the 14th ultimo in reply to enquiries contained in the endorsement of the 10th November last, it is further submitted that the vessel's class be also made subject to the chain cables being ~~renewed or~~ examined by May 1944. & renewed at the first opportunity.

Insert in S.R.L:-

Examine or renew chain cables by 5.44.

Amend in R.B:-

3 Dks & Shelter dk	to	2 Dks & Shelter dk
10 BH	to	8 BH to 2nd dk

Insert in R.B:- "Converted to Shelter dk '43"

The Surveyor should be referred to Table 53 & informed that although the equipment material is reduced the amount is not sufficient to alter the Grade (see footnote).

Posted
m. 7. 44
JMB
870

© 2021
J.C.B.
14.3.44.

C.M.B.

Lloyd's Register
Foundation