

Lloyd's Register of Shipping.

OFICINA CENTRAL: FENCHURCH STREET, 71, LONDRES, E.C.3.

Ibáñez de Bilbao, 22

Apartado de Correos 286

BILBAO, 8th June 1942

Dear Sir,

The Owners of the steamer "HABANA", which is at present undergoing repairs and modifications at this port, are desirous of carrying Oil fuel in the double bottom tanks in the zone of the Machinery spaces and they ask what would be the minimum requirements of the Society, to enable this to be done.

A plan of the tank top plating in way of the Machinery spaces is forwarded herewith, On the plan is indicated the disposition of the new oil fuel bunkers, tank divisions and cofferdams, &c.

We shall be glad if you will kindly let us know as soon as possible the minimum requirements of the Committee in this case.

We are, Dear Sir,

Yours faithfully

For the Surveyors

the Secretary

GLASGOW.



© 2021

Lloyd's Register
Foundation

010461-010465-0122

Referred to the Chief State Surveyor

17 JUN 1942

HB

19 JUN 1942

Reg. early
reply

Requiere to retain a 'dog' of

Requiere de Conces 388
Requiere de Bupso' 33

ORIGINAL CHART: REQUISITION 21888. AT LONDON: E.C.2

LONDON



© 2021

Lloyd's Register
Foundation