

COPY

LLOYD'S REGISTER OF SHIPPING

ENCLOSURES 71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

30th November, 1960.

Classn. (H)

Dear Sirs,

s.s. "DELUNGRA"

I acknowledge receipt of your cablegram and confirm mine as per attached copy.

I enclose herewith a copy of a memorandum detailing what is required so far as the hull is concerned to entitle the ship to be reclassified in the Society's Register Book.

Complete Engine Survey, Main Boiler Survey, Screwshaft Survey and Steam Pipe Survey are required. Spare gear and fire extinguishing arrangements must be to Rule requirements.

As regards the machinery the vessel's class was previously subject to main injection valve chest being renewed at the next drydocking.

Yours faithfully,

Clerk to the
Classification Committee.

The Surveyors,
HONG KONG.



© 2021

Lloyd's Register
Foundation