

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 9166

7th July, 1958.

(S)
LAB

Dear Sir,

Steamer "APURE"

With reference to Jacksonville Report No. 2150, I shall be glad if you will ascertain from the Surveyor, and let me know, why he recommended that only 30 fathoms of chain cable should be renewed as it would appear from the report that all of the chain cable on board this ship is worn to renewal diameter, i.e. 1.23/32".

Yours faithfully,

~~pro~~ Clerk to the
Classification Committee.

The Secretary,
NEW YORK.



© 2021

Lloyd's Register
Foundation

010484-010494-0406