

grams: Nymdible, New York

Telephone: WHitehall 4-0220
4-0221
4-0222
4-0223



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

RECEIVED 17 Battery Place,

New York 4, N. Y.

20 OCT 1958

October 17, 1958

AIR MAIL

The Secretary

LONDON

"MAYMERE"
S.E.A.C. Coaster Type C

Dear Sir:


You will have noted from the copy of our letter of September 24th, addressed to the Owner's representatives, that the above vessel is now engaged in trading outside the limits of service for which she is classed and for which the Honduran Load Line Certificate is valid.

No reply has yet been received from the Owners as to their intentions and in order to enable us to investigate the case in this office I will appreciate your advising me what structural alterations if any have been carried out on this ship since building.

Yours faithfully,

W. R. Smith
Principal Surveyor

last
(1)



© 2021

Lloyd's Register
Foundation

010484-010494-0444

52

Class

COPY TO FBO

R. 17.

See next dated 26/10/58

Section 19

ВЛИВЪ НА РЕКИ

This office I will appreciate your advising me what structural alterations it may have been carried out on this ship since this date. No reply has yet been received from the Owners as to their intentions and in order to enable us to investigate the case in this office I will appreciate your advising me what structural alterations it may have been carried out on this ship since this date.

It is classed and for which the Hongkong Land Certificate is valid. It is now engaged in trading outside the limits of service for which the Certificate is valid. The above vessel, that the above vessel, letter of September

Dear Sir:

U.S.A. Coast and Geodetic Survey

HERMYSAM

ПОДВОД

the 2000s

8261, 71 redof20

NEW YORK, N. Y.

© 2021

THE BAKER PLACE,

UNITED WITH THE BRITISH CORPORATION REGISTER

1
FLOYD'S REGISTER OF SHIPPING



Προϋποθέσεις: 1. Ημερομηνία: 2017

1. *Indistinct* : *Indistinct*

4-0553
4-0555
4-0551
4-0550