

Received from Chief Ship Surveyor 29 JUL 1952

SHIP'S NAME 'MARKAB'

REPORT s

(Ant. No. 27632  
(Ham. No. 1796  
(Bm. No. 418

Outstanding Conditions of Class: Subject to 30 fathoms of chain cable being supplied at the earliest opportunity, and to indented keel plate and bottom shell plates A.2 (p & s) being dealt with by the Special Survey.

of Class (B) (As before ~~or None~~)

SPECIAL SURVEY (B) due 3,53.

Present Survey: (Afloat and in dry dock) Commencement of Special Survey.  
Damage repairs - heavy weather, collision and to the above.  
Equipment-supply of 30 fms. c.c. as above.

atures:

in Certificate in order (Yes-No-None)

standing: (~~If any for S.S. or A.S.~~) See Ant. Rpt. No. 27632

be completed by: 5,53.

ation: SUBMITTED record of docking 5,52 be assigned, but without special condition.

5,52 Ant. Without.

ENDORSEMENT OF CLASS (B).

Indents in side shell plating (p & s).

Delete from R.B.

Cargo battens not fitted



© 2021

Lloyd's Register Foundation

01045-010501-0295