

PHOCAN SHIP AGENCY LIMITED.  
SHIPBROKERS.

Directors

and N. Eustathiou, Greek.

H. Hastings.

E. E. Kulukundis, British (Greek Origin)

Office: Mansion House 1466/8.

Telegrams: Phokais, Stock. London

Telex: Phokais, London

Reference

Reference ME/PP

23, Lime Street,

London, E. C. 3.

8th April, 1949

RECEIVED

9 APR 1949

ANSD.....

The Lloyd's Register of Shipping,  
71, Fenchurch Street,  
London, E.C.3.

Dear Sirs,

S.S. "MARKAB" ex "Empire Mauritius"

The present tail end shaft of the above mentioned vessel was found cracked in the ~~key~~ way upon dry docking the vessel in Antwerp during March.

The Bronze Liner, according to our Marine Superintendent Engineer was in perfect condition, and no doubt upon obtaining information from you representative in Antwerp he will agree with our statement. We should therefore like to know if it will be with the approval of the Lloyds Society of Surveyors if we use the old existing Bronze Liner with the new shaft which we intend to order immediately.

Apart from this saving the Owners a substantial amount of money it will certainly save a lot of time and the delivery of the tail shaft will only be approximately two months instead of ~~from~~ 5/6 months.

Awaiting your reply,

Yours faithfully,

FOR AND ON BEHALF OF

PHOCAN SHIP AGENCY LIMITED

*M. H. Eustathiou*

DIRECTOR

© 2021

Lloyd's Register  
Foundation

being specially examined at the next dry docking and to (B.) slightly

616445-010501-0326



Referred to Mr. Perris.

Insert

*RS*

Submitted for approval provides the  
air can be removed without being  
the Surveyor's satisfaction. work carried out - L

L. J. 9/4/49.



© 2021

Lloyd's Register  
Foundation