

23 JUN 1959

Received from Chief Ship Surveyor

SHIP'S NAME "WELLINGTON"

REPORT

Smk.

No. 953

GB

Outstanding Conditions of Class: SUBJECT to 45 fathoms of worn chain cable on board being renewed at the earliest opportunity.

Endorsement of Class (B) (As before ~~None~~)

Surveys due: SPECIAL SURVEY (C) due 8,60.

Nature of Present Survey: (Afloat and in dry dock)

Docking: Commencement of Special Survey:
Wear and tear repairs including part S.R.L.Appendix items.

Special Features:

Is Interim Certificate in order (Yes-~~None~~)

Items Outstanding (if any for S.S. or A.S.)

FOR PORTION OF SURVEY HELD:- See this report.

S.S. to be completed by:

Recommendation:

SUBMITTED record of 'DS 5,59' be assigned, subject as above, and to wasted shell plates B.17 and H.16 (p.s.) and B.16 & F.17 (p & s) being specially examined and dealt with by the Special Survey.

DS 5,59 Subject

S.R.L..APPENDIX NOTE (AMENDED).
Tank top plating in No. 2 hold and thrust recess indented. Indents in E.7 & F.8 (s.s.f).

S.S.PART HELD.

NOTE:- It would appear from this report that the condition of class regarding 45 fathoms of chain cable may be dealt with in September next.

ENGR. SURVEYORS TO NOTE - Rpt.8.

