

amplified if necessary in the body of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated

Received from Chief Ship Surveyor..... 113 SEP 1961

P'S NAME "SANROCCO" REPORT ROT. No. 52430

EA
standing Conditions of Class:

SUBJECT to indented shell plates K.2, A.2 & 3 (p.s.f) and No.1 in 4th strake below sheerstrake being specially examined and dealt with as necessary by the next drydocking. ACTION is DEFERRED for Special Survey.

L. Appendix. (As before or None) ~~XXXXXXXX~~

veys due: SPECIAL SURVEY (C) due 3,61. - commenced Gen.4,61. Proposal to postpone Special Survey until 3,62 approved 12.4.61 subject to a satisfactory General Examination being held. General Examination commenced Gen.4,61.

ure of Present Survey: ~~(At sea)~~ in dry dock)

Docking:- Completion of the General Examination.

cial Features:

nterim Certificate in order (Yes-No-None) ~~XXXXXXXX~~

~~is Outstanding (If any for S.S.)~~

FOR PORTION OF SURVEY HELD:-

See List in Ship Reports Dept.

to be completed by:

mmendation:

D.57.61 SUBJECT as above, but ACTION continue to be DEFERRED for Special Survey.

SUBJECT. D.57.61

IN S.R.L. APPENDIX.
Boat deck plating etc. (s.s.) set down and shell plate C.9 (p.s) indented. (Waviness in shelter deck plating to be kept under observation).

IT IS FURTHER SUBMITTED postponement of the Special Survey until 3,62 merits approval.

27.0
11/9/61



© 2021

Lloyd's Register Foundation

S.S. PART HELD.

010605-010614-0216

Blk (new)

MONDAY 18 SEP 1961

TEL
OST.