

Received from Chief Ship Surveyor 17 OCT 1961

SHIP'S NAME "SANTA IRENE" REPORT YKA No. 3844

EA

standing Conditions of Class:

SUBJECT to wavy bottom plating (p & s amidships) indented sheerstrake and strake below abreast forward corner of bridge house and in way of No.2 hold (s.s.) being specially examined and dealt with as necessary by completion of the Special Survey.

ACTION is DEFERRED for Completion of the Special Survey.

L. Appendix. (As before or None)

Keys due:

SPECIAL SURVEY (C) due 4,61. Postponement until 4,62 approved 2.8.61 following a satisfactory General Examination.

re of Present Survey: (Afloat and in dry dock)

Temporary repairs to stevedore damage.

al Features:

Interim Certificate in order (Yes-No-None)

Outstanding: (If any for S.S.)

ALL ITEMS Except examination of tween decks.

to be completed by:

4,62.

Recommendation:

SUBJECT as above and to indented No.3 D.B.tank top plating (s.s.) being specially examined and dealt with as necessary next drydocking, but ACTION continue to be DEFERRED for Completion of the Special Survey.

SUBJECT.

IN S.R.L.APPENDIX.

Indents in shell plating (p & s).  
Wing plates (p & s) of aft DT bulkhead buckled.

OFFICE NOTE.

Bottom stiffening fitted in Nos.2-7 D.B. tanks inclusive, except two inner row in way of No.6 (Nwc.2,48 & Rot.10,50).  
Inner bottom stiffened in Nos.2,3 & 4 D.B.tanks (Nwc.2,48 & Rot.10,50).

S.S. PART HELD

