

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME ROCKSIDE. REPORT Bal No. 9256.For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey grounding - damage. When due.....Noted

No outstanding requirements.

Action is deferred for dry docking (grounding)

Indent in S. R. L.

Dry dock. (grounding)


Endorsements of class B'.

Indents in shell plating etc. (415).

almost forecast.

2. Bow anchor & stream anchor

to submit to Statutory Test.

ADM.
12-2-51

© 2021

Lloyd's Register
Foundation

010720-010726-0032