

COPY

# LLOYD'S REGISTER OF SHIPPING



Port GLASGOW.

Date 9th March, 1961.

This is to Certify that I have

Surveyed the M.S. "SILVANA TOMEL" (EX. "AGATE") of Viarescio  
as she lay on the slipway at Bowling on the 3rd March, 1961  
and subsequently on account of Docking Survey and Damage stated  
to have been sustained by ranging alongside jetty at Trevor,  
N. Wales, during heavy weather on the 10th January 1961,

and that I am transmitting to the Committee of Lloyd's Register of  
Shipping, London, a Report, stating that all repairs recommended by  
me have been completed to my satisfaction, also that I am

Recommending that she be continued as classed and to have  
record of drydocking, D.S. 3,61 subject to indented shell  
plates D.3 and 4 and E.3 (s.s.f.) etc., being specially  
examined and dealt with as necessary at the next Special  
Survey.

*T. S. Patkin*

Surveyor to Lloyd's Register.

### KEY TO ABBREVIATIONS

AS	Annual Survey
BIS	Biennial Survey
DS	Docking Survey
NS	Cargo Battens not fitted (No Sparring)

SS	Hull Special Survey
SS(Dr)	Hull Special Survey (Drilling)
SS(M)	Hull Special Survey (Modified)
SS(P)	Hull Special Survey (Progressive)

(T.S. PATKIN)

© 2021

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-  
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."