

17 DEC 1941

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME STRATHALLAN Rpt. Bom No. 6638

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/32.*)

Nature of Survey

The class is subject to permanent repairs to indented shell plating etc. (p.s.a) at the Owners' convenience.

The BOMBAY Surveyor reports (9.41) the vessel placed in dry dock, bottom coated and the decks, hatchways etc. examined.

It is submitted the vessel appears worthy to remain as classed with record of survey 9.41, subject as above.

100A1)	
With fbd)	Subject, etc.
9.41 Bom)	
Fitted for oil fuel etc.)	



© 2021

Lloyd's Register
Foundation

010783-010790-0193