

15 FEB 1963

Ship's name "CHOPIN" Port Csb, No. 58/623
Last survey date 27.1.63.
Class is subject to the 10th length of anchor chain cable being
 tested at the earliest opportunity.

S.R.L. Appendix (as before ~~XXXXXX~~)

Nature of present survey (afloat and ~~in drydock~~)

Examination afloat for possible damage on account of
 H.W. and encountering ice.

Recommendation

SUBJECT as above, but further ACTION be
 DEFERRED for examination in drydock (H.W. and ice).

SUBJECT

INSERT IN ~~S.R.L.~~
 (Drydocking (H.W. and ice). ~~to note.~~

IN ~~S.R.L. APPENDIX.~~
 (Main structure partly of P.403 Steel).

NOTE - Notation "Class Withdrawn at Owners' request"
recorded in the Register Book 25.1.63.

C.S.S. Records Dept.

to note.

© 2021

Lloyd's Register
 Foundation

RSD
 15/2/63