

## COPY

Ship's name

"CHOPIN"

Port

Csb,

No. 58/623

Last survey date 27.1.63.

Class is subject to

the 10th length of anchor chain cable being tested at the earliest opportunity.

S.R.L. Appendix (as before ~~or none~~)Nature of present survey (afloat and ~~in~~ drydock)

Examination afloat for possible damage on account of H.W. and encountering ice.

Recommendation

SUBJECT as above, but further ACTION be DEFERRED for examination in drydock (H.W. and ice).

SUBJECT


INSERT IN S.R.L.

(Drydocking (N.W. and ice).

IN S.R.L. APPENDIX.

(Main structure partly of P.403 Steel).

NOTE - Notation "Class Withdrawn at Owners' request" recorded in the Register Book 25.1.63.



© 2021

Lloyd's Register  
Foundation

010797-010804-018