

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

28th July, 1922.

James,

With further reference to the case of the "KURLAND".  
Question of the second deck stringer and plating was  
discussed with the Falmouth Surveyors, and we are now informed  
that the thickness reported by them is an error, and should  
have been .39. The figures, therefore, agree with those  
reported from the Glasgow Office.

The freeboard report has not yet been received, but  
we expect it in a few days, when the minimum freeboard  
to be assigned will be assigned.

I am leaving on holiday tomorrow, and will be in  
London next week, <sup>when</sup> ~~and~~ I hope to have the pleasure of seeing  
you at the Office, and I will discuss the case with you then.

With kind regards,

Yours faithfully,

Montgomery,

GLASGOW.



© 2021

Lloyd's Register  
Foundation

010858-010865-0327