

Lloyd's Register of Shipping.

Ship's Name "DON JOSE"

Official No.

(Extract From Rpt. 8 dated 13th August, 1941 at Hong Kong)

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in

Fittings and appliances for the protection of openings, guard rails, freeing ports and means of access to crews quarters examined and found in good order.

• Closing appliances as per Load Line Certificate checked, freeboard verified and found in order. Survey form and verification form sent to New York. Certificate endorsed.

TO COMPLETE S.S. NO.1.

Nos. 2, 3, 4, 7 and 8 double bottoms to be examined internally and tested.

Nos. 2, 3, 4, 5 and 6 lower holds and masts and rigging to be examined.

REPAIRS:- Wear & Tear

50 Hatch cleats renewed.

CHAIN CALBES.

135 fathoms 2, 11/16"

75 " 2, 3/4"

90 " 2, 13/16"

30 " 2, 7/8"

330

(Sgd.) Chas. R. Rowcliffe.

Noted RWR

10/11/41