

2m.9.20.

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME Steel Tow Barge "REDSTAR". Rpt. Mtl. No. 3227**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Signature of Surveyor .....

It is submitted before this case receives the consideration of the Committee the Surveyor should be requested to state whether the equipment of anchors and cables is correctly reported in view of the equipment shewn on the approved plan.

It is concluded the decks and bulkheads have been hose tested as required, but the Surveyor should be requested to state if this is so.

Hr. 11/6/30



© 2021

Lloyd's Register  
Foundation

11.6.30.

010933-010942-0039

" " " Through Plate or  
Intercostal Plate...}

Spacing.....