

Mari II

Ply. 7503.

No plans of Machinery have been  
submitted for consideration.

It is submitted the Surveyor be requested to  
forward a J.E. report on the Engines & Boilers.

He should also forward on a report 13 particulars  
of the electrical installation & state whether  
it is in accordance with or equivalent to the  
Rules.

WJ 6/2/42



© 2021

010987-010991-0030

Lloyd's Register  
Foundation



ankshaft journals.

2.3 5.33 5.33 5.33 5.33 2.33 5.33

rust shaft.

2.33

intermediate shafts.

5.33

in compressors.

5.32

iliary oil engines

3-2 eye

all No 1, 3 (7.31)

No 2 7.31 (Mod)

No 3 (Port)

all 12.32

No 1+2 (all)

5.33

iliary Compressors.

1 Elec. + emerg. steam

Emerg 8 (Steam)

4.33

No 1+2 5.33

No 3 12.32

Manoeuv.

5.33

rting air receivers.

2

for 3.31

alt 2.32

alt 5.33

ection air receivers, Main Engines.

2 Wob. 25 span

all 5.33

Aux. Engines.

for No 2, 7.31

No 1+2

5.33

connections.

11.31 5.33

Pumping arrangements.

5.33

os. Lub oil Bilge

11.32

Ballast  
cool water 5.33

fuel storage tanks.

Daily Service tanks.

5.33

eller and outside fastenings.

5.32 5.33

Steel fittings

5.33

2.31

Rot. 22038 4.33

Shi 3278

Shi 43234 11.32

Osl 5.33

DBS 5.33

31

Shi 3287 L

Shi 3955 11.32

" 11.33

31

Osl 3790 CR

Ham 20585


31

Ant 18222

Ham 2.33

31

Shi 2.33



Lloyd's Register  
Foundation