

## COPY

Ship's name

"GLORY"

Port

Sba.

No.

6512

Last survey date

4.2.63.

Class is subject to

buckled stem and stem plating also leaky  
bottom shell plating in way of No.4 hold being specially  
examined and dealt with as necessary by the Special Survey.

ACTION is DEFERRED for Special Survey also  
for examination in dry dock after grounding.

S.R.L. Appendix (as before or none)Surveys due

SPECIAL SURVEY (C) due 10.61. Postponement until  
1.63 approved 6.12.62. G.E. held Sng.10.62. Further  
postponement until 2.63 approved 18.1.63 on the understanding  
that the ship will not be trading outside the Indonesian  
service limits and the deferred items, as above, are specially

Nature of present survey (afloat and in drydock) examined and found in  
(satisfactory condition meantime.

Wear and tear repairs to wasted deck plating etc.

Is interim certificate in order

Yes/No/Nonexx

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by 2.63.Recommendation

SUBJECT as above, and to trunk deck plating  
on portside of No.3 hatchway (wasted) being  
specially examined and dealt with as necessary  
by the Special Survey by 2.63 and for  
examination in dry dock after grounding.

SUBJECT

IN S.N.L.

Drydocking (grounding).

It is stated the ship will be arriving  
at Singapore for the Special Survey about  
the first week of March 1963.