

22 APR 1964

Ship's name "PENELOPE" Port Pir No. 10866

Last survey date 21.3.64.

GB Class is subject to

bottom shell plating and tank end between Nos.1 & 2 D.B.tanks(ss)(leakage) being specially examined and dealt with as necessary by the S.S. - tank not to be used for O.F. meantime, also to indented shell plate No.5 in 2nd below sheerstrake and Nos.4 & 5 in 3rd below sheerstrake with framing in way (p.s.f) being specially examined and dealt with as necessary by the S.S. ACTION is DEFERRED for S.S. by 6,64.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)

Surveys due SPECIAL SURVEY (C) due 6,63. Postponement until 6,64 approved 19.7.63. G.E.held 5,63.

Nature of present survey (~~XXXXXX~~) in drydock

Minor repairs: Deferred repairs to rudder.

Is interim certificate in order Yes/No/None ~~XXXXXXXXXX~~

Items outstanding if any for SS  
ALL ITEMS (See letter of 5.2.64.)

SS proposed to be completed by 6,64.

Recommendation

SUBMITTED record of 'DS 3,64' be assigned, subject as above, and to the rudder and steering gear being lifted and dealt with as necessary at the S.S. but further ACTION be DEFERRED for S.S. by 6,64.

DS 3,64. Subject

IN S.R.L. APPENDIX.

Upper deck plating abreast No.6 hatchway (p.s) indented

*Weardom not taken*  
*[Signature]*  
22/4/64



© 2021

Lloyd's Register Foundation

*DRM*  
*14-4-64*

X