

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

ME

"TELOK VI"

REPORT Dja.

4 E
8 MAY 1953

No. 3644

Orders of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points set in the endorsement. — Extract from Sub-Committee's Report, 24/5/52.

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

This vessel was built in 1950 and classification is now desired.

Plans of straight shafting and pumping arrangements have been revised with some amendments.

Plans of electrical equipment have been requested but not received.

A General Examination of the machinery has been carried out but First Entry Reports yet received.

A reply is awaited as to whether the Owners desire the Torsional Vibration Characteristics of the main propelling machinery to be investigated.

IT IS SUBMITTED action be deferred.

IT IS FURTHER SUBMITTED Djakarta Surveyor be informed First Entry Reports 4b and 13 also Rpt. 9 on classification survey are awaited, together with replies to the various points raised in Secretary's letter of 16.4.53 regarding shafting, pumping arrangements and electrical plans.

cc L.R. 16/53
✓

12/5

End

7.5.53.



© 2021

Lloyd's Register
Foundation

011032-011036-0085