

4.

**COPY**

**LLOYD'S REGISTER OF SHIPPING**

UNITED WITH THE BRITISH CORPORATION REGISTER

Port of SPLIT

5th September, 1952


Dear Sirs,

With reference to the  
Survey now being held on the Steamer  
S.S. "KOSTRENA"

I beg to inform you that, in consequence of  
the condition of this vessel's rudder head

it will be my duty to recommend to the  
Committee that the same be renewed  
before the end of February 1953  
as provided for in the Rules, extracts from  
which appear on the other side:—the con-  
tinuance of the vessel's character in the  
Society's Register Book to be subject to the  
due fulfilment of this condition.

Yours faithfully,



Engineer Surveyor to Lloyd's Register.

To Messrs. JADRANSKA LINIJSKA  
PLOVIDBA, RIJEKA

2m.7.50

011047.011056-0142

Lloyd's Register  
Foundation

## LLOYD'S REGISTER OF SHIPPING,

71, Fenchurch Street, London, E.C. 3.

### Extract from the Rules of the Society respecting Engines and Boilers:—

In the event of either the machinery or boilers appearing to be impaired to such an extent as renders it desirable that either or both be specially surveyed within the prescribed periods, Certificate for either machinery or boilers for a limited period will be granted according to the nature of the case.



© 2021

Lloyd's Register  
Foundation

Did the Surveyor  
What special  
Surveyor to  
State latest  
Did the Survey  
Did the Survey  
Did the Survey  
Did the Survey  
Has the screw  
Has shaft now  
Is an approval  
stern bush  
Has the insul  
**Engine parts**  
If the Survey  
**DOCKING**  
found  
**BOILER**  
and fa  
and ab  
valves  
**DAMAGE**  
25th J  
with n  
steeri  
Steeri  
**General**  
(St  
also c  
S.L.M.  
The ma  
of BS 8  
Survey Fee (