



# LLOYD'S REGISTER OF SHIPPING

Rua da Candelaria 80, 6th Floor,  
(Caixa Postal 4481), Rio de Janeiro

Telegrams: Surveyor, Rio de Janeiro

Telephone: 83.2523

13th. November, 1961.

Reference

"C"

Dear Sir,

Steamer "DOM JOSÉ" ex "SÃO PAULO".

Your letter of the 24th. October, 1961 has just been received and in reply we have to report as follows:-

We confirm that the forced draught fans were examined at this time and regret that this was not made clear in our report.

Concerning the Class Conditions placed against this ship, prior to her Class being expunged in 1,60., we have to state that these items have been dealt with at this survey and the ship placed in good order. A number of fitted cement boxes were also removed and the necessary permanent repairs effected, all as required and found necessary.

Yours faithfully,

For the Surveyors.

The Secretary,  
LONDON.

AIR



© 2021

Lloyd's Register  
Foundation

the  
advise  
it is  
is

M.  
10.61

SR/ER.

REPORTS

*mm*

*Q*

*20/11/01.*



© 2021

Lloyd's Register  
Foundation

1.500.461 Bll.

Minn