

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and in detail the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of

(Reclassification Contingent)
Fixed to oil fuel.

MEMORANDUM

7 AUG 1946

m: LLOYD'S REGISTER OF SHIPPING, 71, FENCHURCH STREET,
LONDON, E.C.3.

(Ref. H.)

The Surveyor(s) at BOMBAY.

essel's Name: S.S. "BULAN".

estion:

With reference to the entry in your return of vessels under survey for the Quarter ended December last, I have to point out that this vessel's name does not appear either on your Quarterly Rtn. 4 or Monthly Rtn. 5B for March last, and I shall be glad to learn how the case now stands.


swer:

BOMBAY

Date: 27th June 1946.

This vessel is still under survey and regret it was omitted from Return 4 for March last. Report on this vessel will be forwarded on completion of the Survey.

J. Bom 12 45 Nelson LMCBS



T. H. Noel

Lloyd's Register
Foundation