

LEPHONE No. 5517.



SURVEYOR:
L. H. WEHRMEYER.

Lloyd's Register of Shipping,

Botanicuslaan No. 23,

Haren-Groningen, The 7th of June 1938.

LLOYD'S REGISTER
Received
9 JUN 1938
And.
LONDON

Dear Sir,

Reverting to my first entry report No. 5^b regarding the M.V. "MARALI" I regret to must say that the marks of identification of the crankshafts of the auxiliary engines are 2878 and 2879 in stead of 2880 and 2881 as mentioned in my report.

I am, Dear Sir,

Yours faithfully,

L. H. Wehrmeyer

The Secretary,

London.



© 2020

Lloyd's Register
Foundation

011079-011088-0137

(F9 JAN 1988)

MB

2. *Handwritten signature*

THE

Hein-Cloung,

Вотничуслан No. 33.

Wm. Keiser of Ephraim

RECEIVED
JAN 11 1964
U.S. AIR FORCE
HONOLULU

© 2020

Lloyd's Register
Foundation

CHINESE