

COPY

LONDON

LLOYD'S REGISTER OF SHIPPING

Port of SYDNEY N.S.W.

Date 7th February, 1962

This is to Certify that I have

surveyed the M.V. "BABINDA", 655 tons gross of Suva,
for repairs to fractured frames No. 43 port side; and no. 51
starboard side,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I will
Recommend that she be Continued as now classed, without
fresh record of survey, subject to all conditions at present
attached to the class of the vessel being dealt with as
previously recommended.

J. M. Carlie
Surveyor to Lloyd's Register.
(J. McCarlie)

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BIS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."