



COPY
Kobe Rpt. 9 No. 10126
LLOYD'S REGISTER OF SHIPPING

BI-76720

Port KOBÉ

22nd February, 1962.

This is to Certify ^{we} that I have

Surveyed the Machinery of the M.V. "AZUMASAN MARU" 6993 tons gross of Tokyo as she lay afloat at Mitsui Zosen, Tamano on the 16th February, 1962 and subsequently in their Drydock for CS, ABS and Docking Surveys

and that ^{we} ~~we~~ will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by

me in connection therewith have been carried out to ^{our} ~~our~~ satisfaction; also

that ^{we} ~~we~~ I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

CS (with date) on completion and ABS 2,62 now

and that her Machinery Classification Record be continued in the Book.

Parts now examined :

(C.S. Items only)

Main Engine:- Nos. 2,3,4 & 5 cylinders, covers, pistons & rods, Valves & gears.
Nos. 2 & 5 connecting rods, top ends & guides.
Nos. 3 & 7 crankpins & bearings.
Nos. 2 & 6 journals & bearings.
No.5 intermediate shaft (Nos. 8 & 9 bearings).

Auxiliaries:- O.P.transfer pump (starb'd forward).
O.P. valve cooling pump(port forward).
S.W. cooling pump (starboard outboard).
Reserve S.W./F.W. pump (starboard centre).

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SCS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS (CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS (OG) Tailshaft Survey—Oil Gland

P. Mason & Y. Kojima

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
ever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
Surveyors or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.

0.2 generator diesel engine (port outboard).

See connections.

Port

This is to Certify that I have

and that her Machinery Classification Record be continued in the Book.

(C.S. Items only)

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

Lloyd's Register
Foundation

Survey Fee

Part 55 £30,000.-

Second Surveyor's Fee (if any)