

Motorship "SMOLNY".

The Owners' Superintendent, Mr.N.N.Volkoff, called at this Office today in connection with the subject placed on the donkey boiler of this vessel.

He was informed that as long as the water tube donkey boiler was not used, the fitting of the automatic feed control apparatus and the adjustment of the safety valves of that boiler might be deferred.

*To Mr. S.S. Hill
to note
29.11.29*

J.L.
26.11.29.



© 2021

Lloyd's Register
Foundation

011149-011160-0092