

REPORT of SURVEY for REPAIRS, &c.

DISCLOSED
BOX No. 99

Date of writing Report..... 10..... When handed in at Local Office..... 10..... Port of London

No. in Reg. Book. 37862 Survey held at on the Wood, Iron or Steel Date, First Survey Twin Sc "Violet" Last Survey 1928 19

TONNAGE:— Built at Hong Kong By whom Hong Kong Whampoa Dock Co. Ltd. When 1928 10
GROSS 210 Owners Federated Malay States Railway Owners' Address Penang
UNDER DK. 210 Managers Penang Port belonging to Penang
NET 73

DISCLOSED
SECTION
No. 705

Surveyed Afloat or in Dry Dock? WB=CellDBorDBa Name of Dock 6340 Port HK Destined Voyage For service between Penang & Prai

total capacity tons. FPT feet; u&B feet; f feet }
tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Year Assigned expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>+100 A.1.</u>		<u>+LMC. 10.28</u>
<u>Ferry 10.28</u>		<u>C-L.</u>

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 6340 Port HK
damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ..ft.....ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Summary of Damage Repairs:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dbng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Working of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt). When put on, Month.....Year.....
Platings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats
Frames & Fastenings	Ceiling	Scuppers	Masts, Yards, &c.
Bottom Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained
Stanchions	Rudder	Hatches	(State if wedges removed)
Stems	Steering gear and its connections	Planking of Wood Vessels	Sails
Side Frames	Windlass	Caulking ditto	Equipment letter
Studs	Have Pumps now been examined and found efficient?	Treenails ditto	Anchors, No. of
Transoms	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Cables (State if now ranged)
Decks	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length.....size
Stanchions	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	" (on board)
Bottom Plating		Ditto Ditto at other places ditto	" Rule length.....size
		Stringers, Clamps & Shelves ditto	Hawser & Warps
		Salting (State if examined.) ditto	Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss. No. 1-24 and ptND24, &c."

Survey Fee (per section 20)	£	:	:	Fees applied for,
Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19.....
Printing Expenses (if chargeable)	£	:	:	Received by me.
Second Surveyor's Fee (if any)	£	:	:	19.....

Committee's Minute
Character Assigned
FRI. 5 FEB. 1932
Withdraw classed
mark
Lo. 11/2/32

Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday, 11th February, 1932
Classing Committee's
decision confirmed

Lloyd's Register
Foundation
011171-011185-0011

Is Certificate required? If so, to be sent to