

Chief Surveyors _____

Received from Chief Surveyors _____

SHIP'S NAME Steel S.S. "WEARISIDE". Report Liv. No81767

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/02.)

of Survey _____

When due _____


* 100 A.1. (Steel).

1 Dk. (Steel) "Well Dk. "

FPT 44t. APT 28t.

FK. 3 BH. Cem. Lloyd's A. & C.P. Q86', B9', F24'.

Machinery aft.



25. 1. 21.

It is concluded the breadth of the treble riveted overlap butts of sheerstrake is as required by the rules, but the Surveyors should state if this is so.



© 2021

Lloyd's Register
Foundation

01197-011206-0170