

6m,9,61

4E

Class is subject to

30 MAY 1962

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME....."GLADONIA".....REPORT.....Rot.....No. 53710

Vessel placed on slipway on account of damage alleged to have been sustained due to grounding near to the New Waterway entrance, in January last.

The propeller and screwshaft were found heavily damaged and the bottom plating in way of the engine room damaged to such an extent that the removal of the Main Engine will be necessary in order to carry out the ship repairs. The Surveyor now recommends that Main Engine repairs be subjected to further examination of the machinery installation when repairs are carried out to the hull.

The vessel has been sold and has been towed to the Port of Amsterdam for repairs.

This information is now submitted for the consideration of the Committee.



© 2021

Lloyd's Register
Foundation

29.5.62

011251-011258-0183

20 CONDENSERS (MAIN & AUX.).....

21 STEAM DE HEATERS.....