

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Survey held at Reg. Book. Date, First Survey Last Survey 541 19

86229 on the Wood, Iron or Steel S.S.S. Westcove

TONNAGE: Built at Sunderland. By whom S.P. Austin & Son, Ltd. When 1912 11

GROSS 2734 Owners Westwick S.S. Co., Ltd. Owners' Address

UNDER DK. 2427 Managers James Westall, Ltd. Port belonging to Sunderland.

NET 1597

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell D Bor DBa feet; uE&B feet; f feet Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 98480 Port Nwc

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
100A1	LMC 4.40
4.40	CL
S.S. Shl. 2nd. No 3-440	8.39
Cargo Patterns not fitted.	

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

DISCLOSED SECTION 541

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE			
Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Feet.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length (on board) mean diamr.
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	Fees applied for,	10
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me,	10
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute

Character Assigned Omitted from 1941-2 re-print

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

011316 - 011329 - 0052

been held on the Machinery of the Ship, at such time, of when will it be sent?

Is Certificate required? If so, to be sent to