

Received from Chief Ship Surveyor **17 NOV 1953**

SHIP'S NAME "SHAHIN" REPORT Gen. No. 19607
JD.

Outstanding Conditions of Class: Subject to temporary repairs to forecastle head being specially examined and dealt with as necessary by next drydocking.

ACTION is DEFERRED for drydocking (grounding).

Endorsement of Class (B) (As before ~~EXXNONE~~)

Nature of Present Survey: (Afloat and in dry dock)

Docking.

Temporary repairs to forecastle, as above, specially examined and found efficient.

Examination after grounding (no damage).

2 bower anchors and stream anchor now proof tested.

Recommendation:

SUBMITTED the record of docking 9,53 be assigned as recommended, without special condition.

9,53 Gen. Without.

~~DELETE FROM S.R.L.
Drydocking (grounding).~~

~~DELETE ENDORSEMENT OF CLASS (B).~~



EL
12.11.53
© 2020

Lloyd's Register
Foundation
011360-04367-025