

Report to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "SHAHIN" REPORT N. O. No. 8138.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Grounding When due —

Noted.

Subject to temporary repairs to fore-castle head being specially examined & dealt with as necessary by next drydocking.

ACTION is DEFERRED for drydocking (grdg.)

Insert in S.P.L.

Drydocking (grdg.)

End. of class (B).

2 bower anchors and stream anchor to submit to proof test.



© 2020
Lloyd's Register
3.9.53

Lloyd's Register
Foundation

011360-011367-0133