

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME.....

"RUSHWOOD"

REPORT

Nwc.
Nwc.

110442.
No. 109782.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Triple Expansion with LP exhaust turbine, *hydraulic coupling*
24½" - 40" - 68" - 45.
H.S. 9915 sq. ft.
New MN 504.

If Boilers fitted with forced draught Yes.

Tail Shaft.

If fitted with a continuous liner Yes.

If fitted with an outside gland of approved type No.



This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed LMC 5.53.

"Fitted for oil fuel 5.53 F.P. above 150°F"
3 SB 220 lb. (Spt) F.D.



adll
10.6.53.2021

Lloyd's Register
Foundation