

COPY.

25 SEP 1950

Lloyd's Register of Shipping



Port of Vancouver, B.C.

28th August, 1950.

This is to Certify *that I have*

Surveyed the Steel Single Screw Steamship "LAKE MANITOU" 7162

tons gross of Vancouver, B.C., whilst on floating dock and

afloat for Damage stated caused by Heavy Weather encountered

on various dates and voyages since May, 1949, Docking and Hull Repairs

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all repairs

recommended by me have been completed to my satisfaction, and

that I have Recommended that she be continued as now

classed with fresh record of Docking Survey 8,50


being fit to carry. dry and perishable cargoes

Attwood
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(B.)



Lloyd's Register
Foundation

011485-011492-0144