

Lloyd's Register of Shipping.

Thodor Bowleris

Ship's Name m. s. "CLAIRE T" Official No. 168629

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in _____

At the present annual load line survey in October, 1956, it was noticed that the ash shoot starboard side had previously been dismantled and the holes in the shell plating and deck closed by welded steelplates.

Copenhagen, 8th October, 1956.

B. Hyltning Larsen

Copy placed on board the ship
B.H.L.

*Noted
JMB
31.10.56*



© 2021

Lloyd's Register Foundation