

BY AIRMAIL

COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

28th September, 1956.

Cassn(S)

NAB

Dear Sir

Motorship "PON DAUNG"

With reference to my letter of the 17th July last, a report of survey has been received from the Aden Surveyor, from which it is noted that a number of lubricating oil pipes are missing.

It is recommended that the lubricating oil pipes and connections for the paddle wheel pedestal bearings and feathering gear be renewed on the vessel's arrival at your port, and I shall be glad if you will give the case the necessary attention, in due course.

Yours faithfully,

pro Clerk to the  
Classification Committee

H. C. Waugh, Esq.,  
RANGOON.



© 2021

Lloyd's Register  
Foundation

011636-011645 6291