

2nd October, 1959.


SASA

5 - As recommended.

"ENTERPRISE" 1426 - The contents of this report have been amended. Class has been amended to +100A1 "Oil Tanker" "For service between Kismayu, Lindi, Diego-Suarez, Comoro and Chelle Islands", and the notations recommended by you have been assigned.

I would refer you to the P.S. of the Secretary's letter of 17 July stating that reference to the speed restriction (s) necessary should be included in the Interim Certificate. You should, therefore, issue an amended certificate and forward a copy to this Office.

You should arrange for a notice board to be placed in a prominent position in the engine room with the speed restrictions marked thereon and the tachometer marked at 260-300 RPM and 530 RPM above. You should advise this Office when this has been done.



011646-011656-0312

Lloyd's Register  
Foundation