

TRANSLATION OF LETTER RECEIVED FROM MESSRS. VEB

DEUTSCHE SEEREEDEREI ROSTOCK, DATED 15TH FEBRUARY, 1961

MS "VOLKERFREUNDSCHAFT"

Your letter of the 12th January, 1961 - Classn. (H)

Dear Sirs,

With reference to your above mentioned letter we beg to inform you that the safety valves of the evaporator will be checked by the Supervisory Authorities of the German Democratic Republic on the vessels return on the 18th February. At the same time the steam generators will be subjected to a thorough internal examination.

The safety valves of the donkey boiler have been tested under steam by the engine room staff of the vessel, also the oil firing installation.

The Surveyor of the Technical Supervisory Authorities was handed a report on the subject and the necessary entries have been made in the boiler book.

We shall be glad if you will kindly note the above for the purpose of your records.

Yours faithfully,



© 2021


Lloyd's Register
Foundation

011834-011843-0124

ER.

Owners should
 be advised that
 while the safety values of
 the st. gas economiser may
 be adjusted by the Chief Engineer
 - who should forward the certificate
 to this office - the SVs of the oil
 fired boiler and the evaporator
 should be adjusted by a surveyor to this
 Society

W.M.

 28/2/61



© 2021

Lloyd's Register
Foundation

nfige
 LL
 71
 L
 Bet
 Seh
 Auf
 neitt
 Dema
 18.
 frum
 sen.
 Die
 urc
 tal
 er
 hend
 uch
 LR b
 en u