

ct to

Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

21 NOV 1960

AME.....VOLKERFREUNDSCHAFT.....REPORT.....CPN.....No.18614.....

ABS due 8/60, partly held now.

Docking, Port and starboard tailshafts seen.

CS advanced.


The Surveyor reports some alleged damage sustained to the propellers as a result of grounding and satisfactory repairs now effected.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh record of TS(CL) 9/60 now and ABS 10/60 when the survey has been completed.

For completion of ABS: Safety valves of both boilers to be adjusted under steam and the oil fuel installation to be examined under working conditions.

*and the ex. gas economiser SV's*

For completion of CS: The evaporator safety valves to be adjusted.



© 2021

Lloyd's Register  
Foundation

16.11.60

011834-011843-0140