

011988-011994-0092

5- JUN 1964

Ship's name "NORDIC"

Port

BSB

No. 10342

Last survey date 14.4.64.

Class is subject to

- 1) Starboard propeller being specially examined and dealt with as necessary at the next dry-docking.
- 2) Port main engine cracked aft scavenge crank web being specially examined and dealt with as necessary on the vessel's return to the U.K. this voyage.

SRL Item No. 2. After partial repairs at Sydney to the port main engine scavenge crank forward and aft couplings, the vessel has successfully made several voyages. A thorough examination and hammer test showed everything to be in order for the voyage to U.K.

IT IS SUBMITTED that this vessel is eligible to remain as classed, subject as above, regarding both items.



© 2021

Lloyd's Register
Foundation

1.6.64.