

5 - MAY 1964

Ship's name

NORDIC

Port

SVD.

No. 36808

Last survey date 26/3/64

Class is subject to

starboard propeller being specially examined
& dealt with as necessary at next
dry docking.

Port Main engine

Aft

scavenge

crank web

found cracked

between bolt holes. Crankshaft

realigned and six bolt holes in

coupling bored out & new bolts

fitted. Surveyor recommends

cracked aft scavenge crank web

be examined before vessel

leaves Australian Coast this voyage

& be dealt with on vessels

return to U.K. this voyage.

It is submitted that this
vessel is eligible to remain

CLASSED. subject to above & as recommended



© 2021

Lloyd's Register
Foundation

011988 011994-0097