

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

22nd November, 1965.

C.
DNS/DET

Dear Sirs,

CLASSING LETTER

15012 "FREDRIKA". As recommended.

It is noted that the new screwshaft was found to be in accordance with the Rules for four yearly surveys and, in normal circumstances, this would entitle the Owners to have future Screwshaft Surveys held at intervals of four years but, having regard to the failure of the previous shaft, it is considered that the next survey should be reckoned as becoming due in three years time, i.e. at the end of September 1968.


Provided, on the occasion of the next survey after three years in service, the shaft is crack detected, found in order and the Owners still wish to have future surveys held at intervals of four years then, on application by the Owners, the question will be reviewed in this Office.

Please inform the Owners accordingly.

Yours faithfully,

pro Clerk to the
Classification Committee

The Surveyors,
HAMBURG.



Lloyd's Register
Foundation

011988 - 011974 - 241