

-7 JUL 1965

Ship's Name SS/MS 'EVER HAPPINESS' LR520658  
 Gross tons 6766 Port of Registry Keelung Port Mormugao  
 Date of build 5-1943 Is there a rpt. 8? Yes Rpt. No. 78  
 No. of visits 2 First date 26.6.65 Last date 29.6.65  
 Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? == Last rpt. (H.Q. only)  
 Date of completing rpt. 3.7.65 Surveyed at, if different from Port above  
 Is a rpt. 9A attached? Yes MN 510 Nature of survey General Examination for Postponement of Special Survey.  
 Survey fees Damage fee Expenses S.A. fee

DOCKING

Propeller Sea connections Oil gland  
 Fastenings Wear down of stern bush (if relined, state clearance before and after)  
 Has screw/tube shaft been drawn? Date of examn.  
 Has shaft been changed? Has shaft now fitted been previously used?  
 Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG)	MAIN
Air heaters	
Superheaters	
Safety valves	
Mountings, doors and fastenings	
Safety valves { Sat adjusted to { Spt	
Boiler securing arrangements	
Main economisers	Exhaust gas heated economisers and their safety valves
Steam heated steam generators	Steam generator safety valves adjusted to
Forced circulating pumps	Funnel
Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?	Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed ~~with~~/without fresh record of survey subject to any outstanding conditions of class being dealt with as previously recommended.

ALSO FOR

SPL FOR

TRO

NOTED BY SRI

POSTING

HEADER

CERT

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

See Rpt 9A

THURSDAY - 5 AUG 1965

A. S. V. de Melo Surveyor to Lloyd's Register of Shipping



Lloyd's Register Foundation

011995-012002-0065

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark thereon should be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is