

COPY

Lloyd's Register of Shipping.

UNITED WITH THE BRITISH CORPORATION REGISTER



Port Newcastle N.S.W.

3rd June, 1955.

This is to Certify that I have

Surveyed the Steel Screw Steamer "LADY ISABEL"

of Melbourne

1545 Gross Registered Tons

Afloat after grounding off Cape Edgecumbe 24th May, 1955

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all repairs recommended by me have been completed to my satisfaction, and that I have **Recommended** that she e continued as classed subject to Bottom plating etc. being specially examined at next dry docking and A.P. tank topplate being re-examined at next dry docking


being fit to carry dry and perishable cargo.

For endorsements see back hereof.

Sgd W.B.C. Elder

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or any Surveyor, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



COPY

Lloyd's Register of Shipping

UNITED WITH THE BRITISH CORPORATION REGISTER
Bulwark-plating & (s.s.) abreast No. 2 hatchway

set in.

Indents in shell plating (p & s).



1922

This is to certify that I have

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all repairs recommended by me have been completed to my satisfaction, and that I have recommended that she be continued as classed

subject to bottom plating etc. etc. specially examined at next dry docking and 1/2 ton weights being re-examined at next dry docking

Surveyor to Lloyd's Register

The Certificate is issued on the basis of the Rules and Regulations of the Society, which provide that:—
While the Committee of the Society do their best efforts to ensure that the functions of the Society are executed it is to be understood that neither the Register nor any Member of any of its Committees is under any liability in any report or certificate issued by the Society or in any entry in the Register, or for any error of judgment or negligence of any of the Committees or any Surveyors or other Officers or Agents of the Society.



Lloyd's Register of Shipping
Foundation

TONN
OSS
DER D
T
veye
UDB
al ca
Only
N.E
ast
iodica
omple
xtent
ould
ummar
ould
espect
damage
his ser
PAIRS,
t th
f gr
elbo
See
rom
oft
pon
ound
f th
hat
IMARY
Rene
Rem
Fair
ESENT C
ks
ilking of
mings
ms & Fa
side Pla
mes
erse Fra
igitudinal
nsverses
ors
isons
Ingers
er Botton
ve the Tar
ve the Tar
Gene
upon
of su
lass
top
abre
vey Fee
ocial Dan
(per
Travelling