

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

29th December, 1965.

C
DD/SO

Dear Sirs,

CLASSING LETTER.

322 "NAESS VENTURER". As recommended. It is concluded that to complete the General Examination of the hull in addition to the examination of selected cargo tanks, the following items also require to be examined:-

Fore and aft peak tanks, deckhouses.
Superstructures, skylights.
Companionways, air and sounding pipes.
Bulwarks.

Your confirmation on these points however, is desired.

I would point out that a Report 8 (PS)
(Tanker) Form should have been used for this survey.

Yours faithfully,

pro Clerk to the
Classification Committee.

The Surveyors,
DUNKIRK.

© 2020
Lloyd's Register
Foundation
012124-0128-0033