


Lloyd's Register of Shipping

231 St. James Street West,

Montreal 1.

4th August, 1945



The Secretary
Wokingham -

Dear Sir;-

Montreal Report No. 6591

S/S ROCKLAND PARK - Morton's
Hull No. 61

We herewith enclose FIRST ENTRY Reports, as
undernoted, on the above Vessel;-

Report No. 1
Report No. 4
Report No. 5a (2 Rpts. 1 for each BOILER)
Report No. 13

Copy of Interim Certificate Hull
" " " Machinery

Forging and Casting Certificates Hull
" " " Machinery


Copy of Certificate for Screw Shaft and
Intermediate Shafts -
Copy of Certificate for 8"x4" Steam Auxiliary
Engine - Serial No. 72528-7 (Test Sheets attached)-
Copy of Certificate for 8"x4" Steam Auxiliary
Engine - Serial No. 72528-8 (Test Sheets attached)-

Copies of Anchor Certificates Nos. 5265, 5266, 5270

Copy of Certificate covering position of Ship
Side Openings -

Photostat copies of Boiler Certificates Nos. 4578
and 4579

Photostat copies of Certificates covering Chain
Cables - Nos. 2234, F-11,089, and 2227 -



© 2021

Lloyd's Register
Foundation

The Secretary


- 2 -

4th August, 1945

Photostat copies of Weld Test on the
Boilers Nos. B.1421 P.5 and S.6 -

We are, Dear Sir,

Yours faithfully,



Enclosures
ND:FC

Principal Surveyor in Canada

c.c. The Principal Surveyor - New York



© 2021

Lloyd's Register
Foundation

0082 2/2

50
R.S.

20 AUG 1945



© 2021

Lloyd's Register
Foundation

DOUBLE

Side K

Middle

Floors,

Bottom

Painting

the if F

ameter

in

fr

nes i

th of

verse

anc

FR

MES

h

ST

Register T

13