

19 JUL 1958

Received from Chief Ship Surveyor

SHIP'S NAME "INUISAN MARU"
AR.

REPORT Kob.

No. 5804

Outstanding Conditions of Class: None.

Endorsement of Certificate (~~As before~~ None)

Nature of Present Survey: (Afloat and in dry dock) Special Survey (A) due
6,58; damage repairs;

Recommendation: SUBMITTED record of 'DS 5,58' and Notation of 'S.S. Tmn.
5,58' be assigned as recommended.

IT IS FURTHER SUBMITTED the Surveyors be advised it is con-
sidered:-
CLUDED

- 1) No. 3 D.B. tank has been used exclusively
for the carriage of oil fuel,
- 2) The lubricating oil D.B. tanks were
tested,
- 3) There are 300 fathoms of chain cable on
board this ship and not 270 as reported.

DS 5,58.
S.S. Tmn. 5,58
Blk(new)

© 2021
Lloyd's Register
Foundation
012165 012171-0139